

Update eSID with MaptunerX

Contents

| | |
|---|----------|
| <i>Introduction</i> | 3 |
| <i>Check eSID software version</i> | 3 |
| <i>Compatibility Matrix</i> | 4 |

Introduction

The eSID products has been developed by a very small team (one person) and there hasn't been time available to spend on a secure software update procedure. The first eSID products needed to be shipped to Sweden for update, but due to high custom fees and taxes for citizens outside EU it was not working out for them.

During the development of the eSID3 a secure bootloader was developed and also integrated into the eSID03-06 Gen2 product starting from software 1.2.x in August 2020.

After a cooperation with Maptun Performance it is now possible to update the latest eSID products using their MaptunerX handheld device. The user can purchase an update on their website and it will show up as an App on the device. In order to perform the update a OBD2 Y-split cable is needed to connect both/all eSID(s) and MaptunerX together in the vehicle.

Note: It is important that the OBD split cable has all the 16-pins and cheap ones sometimes doesn't.



Map Tun
performance



Check eSID software version

On the eSID1, eSID2 and eSID3 the version is displayed on first startup. Just disconnect the unit from the OBD connector, connect it again and start it up.

On eSID03-06 the software version for the two nodes can be shown under the "Diagnostics" group.

Compatibility Matrix

| Product | Released | Software | Update software with MaptunerX? |
|---|----------|---|---------------------------------|
| eSID1  | 2013 | x.x.x | No |
| eSID2  | 2014 | SAx.x.x | No |
| eSID3  | 2020 | SGx.x.x | Yes |
| eSID03-06 Gen1  | 2017 | SBx.x.x SCx.x.x | No |
| eSID03-06 Gen2  | 2018 | SD1.1.x and earlier SE1.1.x and earlier | No |
| | | SD1.2.x and later SE1.2.x and later (Units sold after Aug-Sep 2020) | Yes |